


Operating instructions for the baseboard ADA9

The cooperation between the MOPSIcdLX and the baseboard ADA9 causes an error in the LAN environment. The MOPSIcdLX owns a network transformer and the baseboard ADA9 owns a transformer (integrated within the connector).



The only way to bypass this issue is to use a separate cable adapter. An appropriate cable is available from KONTRON (KAB-MOPS-ETN1, part number 96048-0000-00-0).

