Errata **1**

Manual: 26172

Manual Index: 01

Table of Contents:

This page has been intentionally left blank.

1. Reference: Page 2-11, Chapter 2.3.1, Table 2-2

The referenced information is revised as follows.

The original Table 2-2 entries for pins 60 and 61:

Table 2-2: Pinout of CON1 (Pn1) Connector

PIN	SIGNAL	TYPE	SIGNAL GROUP	REMARKS
60	INTA#	I/O	PCI	
61	PCI-CLK-OUT-2	O	PCI	Master Mode: internal pull-up: 2.7kΩ; Slave Mode: no pull-up

are changed to read:

Table 2-2: Pinout of CON1 (Pn1) Connector

PIN	SIGNAL	TYPE	SIGNAL GROUP	REMARKS
60	PCI-CLK-OUT-2	O	PCI	
61	INTA#	I/O	PCI	Master Mode: internal pull-up: 2.7kΩ; Slave Mode: no pull-up

This page has been intentionally left blank.