

[PLX8R116](#)

The last valid Bios revision for the old hardware.

Do not use the Bios revision PLX8R116 for the new hardware revision 7.0 or greater.

Do not use the Bios revision PLX8R2?? for the old hardware revision up to 7.0.

(Check the System Bios Setup entry 'Board Information')

Difference: The type of Super-I/O has changed.

[PLX8R204](#)

Bug fix: The new Super-I/O only supports 12 MHz as keyboard/mouse clock. The System Bios Setup has allowed the setting of several clock frequencies. Now the Bios works with a fixed 12 MHz clock.

Bug fix: Added the PS/2 mouse entry in the PnP Bios extension. The Linux operating system did not detect the PS/2 mouse.

[PLX8R203](#)

Bug fix: If the board works without a battery possibly some CMOS values are not defined. The System Bios checks the battery status and clears all CMOS values if no battery is connected.

[PLX8R202](#)

New feature: Removed the power-button support in the System Bios (based on a hardware modification).

[PLX8R201](#)

Bug fix: Changed some JIDA32 features to the new Super-I/O requirements.

Bug fix: Corrected a bug within the UDS/DisplayID module if the DE signal referred to fixed low or high level.

New feature: Some DMI entries modified.

[PLX8R200](#)

First mass production Bios for the new hardware.