

This is release notes for
VxWorks 6.8 / Workbench 3.2 Board Support Package (BSP) release for
Kontron KTUS15/mITX board.

BSP version R01.00 (1 September 2010)

Limitations:

- Supports SATA controller AHCI/RAID mode only;

Changelog:

Changes from R00.00 to R01.00:

- Add RTC, HAL components;

n/a

Known issues:

- Boot loader hangs with attached USB keyboard (affected by BIOS enabling legacy USB support);
- Boot loader fails to autoboot OS image over FTP connection without network mask;
- OS image fails to load "vxworks.sym" file with explicit defined network mask;
- Error message "usrAtaConfig: controller is out of range (0-0)" shows up during bootloader/OS image launch.